



# TRANSMISSION

DIGEST

# 2008


# Technical Directory



Audi 09G/09M: Cross-connection of electrical components (Technically Speaking) . . . . .	<b>October</b>
Audio A8 Quattro with ZF 5HP24: TCC cycling bang (TASC Force Tips) . . . . .	<b>August</b>
Avoiding after-overhaul problems - R&R tips (TASC Force Tips) . . . . .	<b>January</b>
AW TF60-SN (09G/09K/09M): Failure of C1/K1 clutch (Technically Speaking) . . . . .	<b>November</b>
AW TF60-SN (09G/09K/09M): Solenoid control (Technically Speaking) . . . . .	<b>November</b>
AW55-50: Differences among vehicle manufacturers (TASC Force Tips) . . . . .	<b>June, July</b>
AW55-50SN: Diagnosing valve-body problems (TASC Force Tips) . . . . .	<b>February</b>
AW81-40LE: Design and operation (Shift Pointers) . . . . .	<b>June</b>
AW81-40LE: valve-body and timing solenoid (Shift Pointers) . . . . .	<b>July</b>
AWF21 (TF-81SC: Failure of C1/K1 clutch (Technically Speaking) . . . . .	<b>November</b>
BMW TF60-SN: Cross-connection of electrical components (Technically Speaking) . . . . .	<b>October</b>
BMW X5 with ZF 6HP26: Melted relief valve blocks fluid flow through pump cover (Shift Pointers) . . . . .	<b>August</b>
BorgWarner 4411 transfer case: Operation & diagnosis (Up to Standards) . . . . .	<b>May</b>
BorgWarner 44-82 transfer case: design, operation & diagnosis (Up to Standards) . . . . .	<b>December</b>
BorgWarner transfer cases: Identification guide (Up to Standards) . . . . .	<b>September</b>
CFT-30 CVT: Whining/thumping/knocking noise from transaxle (Shift Pointers) . . . . .	<b>December</b>
Chevrolet Malibu, 2008: Serviceability report (Tech to Tech) . . . . .	<b>September</b>
Chevy Tahoe, 1996: Low-beam headlamps inoperable (Tech-to-Tech) . . . . .	<b>May</b>
Chevy, 1957 street rod: Malfunction in drive-by-wire system (Tech to Tech) . . . . .	<b>October</b>
Chrysler 41TE, 1995 Cirrus: Diagnosis of codes 41, 42 & 21 (Shift Pointers) . . . . .	<b>October</b>
Chrysler 41TE/41TES: Addition of variable line-pressure-control solenoid in 2007 models (Technically Speaking) . . . . .	<b>May</b>
Chrysler 41TE: Fluid foaming after rebuild (Shift Pointers) . . . . .	<b>May</b>
Chrysler 42RLE: Addition of variable line-pressure-control solenoid in 2005 models (Technically Speaking) . . . . .	<b>May</b>
Chrysler 62TE: design and operation (Technically Speaking) . . . . .	<b>April</b>
Chrysler 68RFE: Rebuilding the torque converter (Torque Converter Tech Tips) . . . . .	<b>August</b>
Chrysler New Yorker, 1991: diagnosis of no-start condition (Tech to Tech) . . . . .	<b>July</b>
Chrysler RWD valve-body-linkage pivot wear (TASC Force Tips) . . . . .	<b>November</b>
Cooler flushing . . . . .	<b>May</b>
Core-handling practices (Up to Standards) . . . . .	<b>March</b>
Detailing: Performing a thorough transmission repair (TASC Force Tips) . . . . .	<b>October</b>
Diagnosing noise problems in manual transmissions (Up to Standards) . . . . .	<b>August</b>
Dual-clutch transmissions: design and operation (Up to Standards) . . . . .	<b>July</b>
Endplay adjustment in rebuilt converters (TC Tech Tips) . . . . .	<b>March</b>
Ford 5R110W: Delayed forward engagement/shudder on takeoff (As Seen in Tech/Talk) . . . . .	<b>October</b>
Ford 5R110W: No TCC and/or DTC P0741 (As Seen in Tech/Talk) . . . . .	<b>April</b>
Ford 5R55W: Delayed engagement (As Seen in Tech/Talk) . . . . .	<b>June</b>
Ford Escape hybrid, 2008: Serviceability report (Tech-to-Tech) . . . . .	<b>June</b>
Ford FNR5: Redesign of transaxle to add fifth gear (Technically Speaking) . . . . .	<b>June</b>
Gears & gear ratios (Commentary by Don Anglin) . . . . .	<b>February</b>
GM 4L30-E: No upshifts from first gear after rebuild; reverse OK (Technically Speaking) . . . . .	<b>February</b>
GM 4T60-E: no TCC application (Shift Pointers) . . . . .	<b>April</b>
GM 4T65-E: 1811 & 741 codes (Torque Converter Tech Tips) . . . . .	<b>October</b>
GM 4T65-E: no TCC application (Shift Pointers) . . . . .	<b>April</b>

GM 6T75: Code P0797 - pressure control solenoid C stuck off (Shift Pointers)	<b>February</b>
GM transfer cases: Electronic diagnosis (Up to Standards)	<b>June</b>
GM trucks with independent front suspension, 1983 up: Revised front drive axles (Up to Standards)	<b>October</b>
Honda: Shifter stuck in park (As Seen in Tech/Talk)	<b>September</b>
Hyundai F4A40/50: shudder or slip in reverse (As Seen in Tech/Talk)	<b>December</b>
Impeller vanes and weld gaps (Torque Converter Tech Tips)	<b>April</b>
Mazda 5NR5: Redesign of transaxle to add fifth gear (Technically Speaking)	<b>June</b>
Mazda R4A-EL: Cross-connection of electrical components (Technically Speaking)	<b>October</b>
Mercedes: diagnosis of electrical problems (Tech-to-Tech)	<b>April</b>
Mitsubishi F4A40/50: shudder or slip in reverse (As Seen in Tech/Talk)	<b>December</b>
More centerline issues (Torque Converter Tech Tips)	<b>December</b>
New Venture 244 Gen II transfer case: design, operation and diagnosis (Up to Standards)	<b>April</b>
Nissan RE4F04A: Abrupt downshift and upshift (Shift Pointers)	<b>September</b>
NVG 245 transfer case: design, operation and diagnosis (Up to Standards)	<b>November</b>
Oldsmobile Bravada, 1994: No upshift; code 24 (Shift Pointers)	<b>March</b>
Rebuilding planetaries: an easier way (TASC Force Tips)	<b>April</b>
Saab 9-3: Service accessibility and issues (Tech-to-Tech)	<b>March</b>
Solving noise problems in manual transmissions (Up to Standards)	<b>August</b>
Stator-cap wear (Torque Converter Tech Tips)	<b>July</b>
TCC frictions bonded off center (Torque Converter Tech Tips)	<b>November</b>
TCC release clearance (Torque Converter Tech Tips)	<b>January</b>
Temperature setting for bonding TCC pistons (Torque Converter Tech Tips)	<b>June</b>
Toyota A140E: Cross-connection of electrical components (Technically Speaking)	<b>October</b>
Toyota A340, 2002 Tundra: No lockup hot, TCC slip, 0770 code (Torque Converter Tech Tips)	<b>September</b>
Toyota Tacoma, 2000: Transmission malfunction caused by defective tow-package wiring (Technically Speaking)	<b>July</b>
Toyota Tacoma: serviceability report (Tech-to-Tech)	<b>December</b>
Toyota U140/240 series: Common wear-out areas in the valve body (Technically Speaking)	<b>September</b>
Toyota U140/240 series: diagnostic information (TASC Force Tips)	<b>December</b>
Toyota U140/240: Operating characteristics (Technically Speaking)	<b>August</b>
Toyota U140E: Use of incorrect manual valve (Technically Speaking)	<b>December</b>
Toyota/Lexus U140/240: Operational characteristics (Technically Speaking)	<b>August</b>
Transmission rebuilding tips to avoid common problems (TASC Force Tips)	<b>March</b>
Tremec 6060: Design and operation (Up to Standards)	<b>February</b>
Volvo 55-50SN: 740 code (Torque Converter Tech Tips)	<b>October</b>
VW 01M, 2001 Jetta: 740 code (Torque Converter Tech Tips)	<b>September</b>
VW 01M, 2002 Jetta: Dragging 3-4 shift (Technically Speaking)	<b>March</b>
VW 09A (JF506E): Code 00349 - electrical fault for solenoid 10 (Shift Pointers)	<b>January</b>
VW 09G/09M: Cross-connection of electrical components (Technically Speaking)	<b>October</b>
ZF 5HP19/24: Noise caused by worn sprag inner race in stator (Torque Converter Tech Tips)	<b>May</b>
ZF 5HP24 in Audi A8 Quattro: TCC cycling bang (TASC Force Tips)	<b>August</b>
ZF 5HP24: Code P0731 or P1722 - gear-ratio error in first (Technically Speaking)	<b>January</b>
ZF 5HP26 in BMW X5: Flow through pump blocked by melted relief valve (Shift Pointers)	<b>August</b>

## Seminar Audio Recordings



### Transmission Technical

Technical Package of 6 CDs .....\$99  
Technical Seminars Individually .....\$19

# 2008



### Shop Management

Shop Management Package of 8 CDs.....\$136  
Individual CD orders.....\$19 each

#### 08-T01 ZF 6HP Factory Training

Direct from ZF, Tony Price brings diagnostic and operating knowledge on this emerging and popular family of transmissions.

#### 08-T02 Chrysler 62TE

Wayne Colonna from ATSG gives the industry's first comprehensive look at the unique workings and technology of this unit destined to become a regular in your shop bays.

#### 08-T03 Voltage Drop Testing

Jerry "G" Truglia gives plenty of advice and hints on successfully and efficiently locating the electronic gremlins that haunt the modern day transmission retailer.

#### 08-T04 Toyota U Series Transaxles

Nobody can cram more knowledge into a seminar session than ATSG's Pete Luban. Here is the definitive builder's guide to working on these popular units.

#### 08-T05 Scoping Late-model Fords

Bernie Thompson from Automotive Test Solutions discusses how to test and interpret the Ford data stream. This session is valuable to anyone working on these vehicle powertrains.

#### 08-T06 The Builder's Bench 2008

John Parmenter moves through a number of units that have challenged rebuilders this year. John identifies the problems and then serves up solutions to both diagnostic and rebuilding issues.

#### 08-M01 Profit Structuring: Installing Winning Formulas, Part I

In this Automotive Management Institute-accredited seminar, Maylan Newton enables shop operators to understand, install and use a set of formulas in conducting business that helps them achieve financial goals.

#### 08-M02 Profit Structuring: Installing Winning Formulas, Part II

In Part II of this seminar, Maylan Newton continues with formulas to help shops set the correct flat rate, conduct business based on the cost of doing business, work on formulas to measure productivity, work parts-markup formulas and plan growth strategies.

#### 08-M03 Sid's Steps for Success

Motivational speaker Sid Hurlbert teaches you coping mechanisms to leave exhaustion and cynicism behind, particularly when dealing with customers, co-workers and even family members. He teaches you how to take control and make your workday more enjoyable.

#### 08-M04 Performance Parts & the Magnuson-Moss Act

Undercar Digest Management Matters Author Tom Langer, Larry Norris of MagnaFlow and Muffler & Pipe Advice author Ed Hanson discuss the dos and don'ts of aftermarket performance parts and how they affect a vehicle's manufacturer warranty.

#### 08-M05 Dealing with Those Pesky Telephone Price Shoppers

Transmission Digest Business Editor Terry Greenhut shows you the best techniques to handle price shoppers over the phone and persuade them to set up an appointment so a technician can determine what is actually wrong with their vehicle instead of quoting a price for an undiagnosed service.

#### 08-M06 Business Management for Automotive Service Businesses

Undercar Digest Management Matters author Tom Langer sets the framework for shops to help you set up a business plan that really works.

#### 08-M07 Cashing In on Classics

Management Matters author Tom Langer, Muffler & Pipe Advice author Ed Hanson, Huth's Joe Becker, Eaton Leonard Tooling's Paul Howard, Packard Industries' Fred Kanter and vehicle restorer and museum owner Dennis Moran discuss how classics and muscle cars can provide an additional profit center for shops.

#### 08-M08 5 Seconds to Success

Motivational Speaker Sid Hurlbert shares some secrets that very few businesses understand. In less than 5 seconds you can determine how customers, co-workers and even family members are going to view and treat you. Sid combines humor with remedies that can make your business prosper.

**HANDOUTS ON CD**  
**PDF Format includes**  
**Management and Transmission**  
**Technical session materials**  
**distributed.**  
**\$50**

Visa and MasterCard Accepted

**U.S. Orders:**  
Includes Postage & Handling  
Allow 4 to 6 weeks for delivery

**International Orders:**  
Please inquire for shipping charges



**Phone: 417-866-3917**  
**800-274-7890**  
**Fax: 417-866-2781**  
**Mail: PO Box 2210**  
**Springfield, MO 65801-2210**  
**E-mail: editor@mdpublications.com**

Make Checks payable to: M D Publications, Inc.