



TRANSMISSION

DIGEST

2008


Technical Directory



Audi 09G/09M: Cross-connection of electrical components (Technically Speaking)	October
Audio A8 Quattro with ZF 5HP24: TCC cycling bang (TASC Force Tips)	August
Avoiding after-overhaul problems - R&R tips (TASC Force Tips)	January
AW TF60-SN (09G/09K/09M): Failure of C1/K1 clutch (Technically Speaking)	November
AW TF60-SN (09G/09K/09M): Solenoid control (Technically Speaking)	November
AW55-50: Differences among vehicle manufacturers (TASC Force Tips)	June, July
AW55-50SN: Diagnosing valve-body problems (TASC Force Tips)	February
AW81-40LE: Design and operation (Shift Pointers)	June
AW81-40LE: valve-body and timing solenoid (Shift Pointers)	July
AWF21 (TF-81SC: Failure of C1/K1 clutch (Technically Speaking)	November
BMW TF60-SN: Cross-connection of electrical components (Technically Speaking)	October
BMW X5 with ZF 6HP26: Melted relief valve blocks fluid flow through pump cover (Shift Pointers)	August
BorgWarner 4411 transfer case: Operation & diagnosis (Up to Standards)	May
BorgWarner 44-82 transfer case: design, operation & diagnosis (Up to Standards)	December
BorgWarner transfer cases: Identification guide (Up to Standards)	September
CFT-30 CVT: Whining/thumping/knocking noise from transaxle (Shift Pointers)	December
Chevrolet Malibu, 2008: Serviceability report (Tech to Tech)	September
Chevy Tahoe, 1996: Low-beam headlamps inoperable (Tech-to-Tech)	May
Chevy, 1957 street rod: Malfunction in drive-by-wire system (Tech to Tech)	October
Chrysler 41TE, 1995 Cirrus: Diagnosis of codes 41, 42 & 21 (Shift Pointers)	October
Chrysler 41TE/41TES: Addition of variable line-pressure-control solenoid in 2007 models (Technically Speaking)	May
Chrysler 41TE: Fluid foaming after rebuild (Shift Pointers)	May
Chrysler 42RLE: Addition of variable line-pressure-control solenoid in 2005 models (Technically Speaking)	May
Chrysler 62TE: design and operation (Technically Speaking)	April
Chrysler 68RFE: Rebuilding the torque converter (Torque Converter Tech Tips)	August
Chrysler New Yorker, 1991: diagnosis of no-start condition (Tech to Tech)	July
Chrysler RWD valve-body-linkage pivot wear (TASC Force Tips)	November
Cooler flushing	May
Core-handling practices (Up to Standards)	March
Detailing: Performing a thorough transmission repair (TASC Force Tips)	October
Diagnosing noise problems in manual transmissions (Up to Standards)	August
Dual-clutch transmissions: design and operation (Up to Standards)	July
Endplay adjustment in rebuilt converters (TC Tech Tips)	March
Ford 5R110W: Delayed forward engagement/shudder on takeoff (As Seen in Tech/Talk)	October
Ford 5R110W: No TCC and/or DTC P0741 (As Seen in Tech/Talk)	April
Ford 5R55W: Delayed engagement (As Seen in Tech/Talk)	June
Ford Escape hybrid, 2008: Serviceability report (Tech-to-Tech)	June
Ford FNR5: Redesign of transaxle to add fifth gear (Technically Speaking)	June
Gears & gear ratios (Commentary by Don Anglin)	February
GM 4L30-E: No upshifts from first gear after rebuild; reverse OK (Technically Speaking)	February
GM 4T60-E: no TCC application (Shift Pointers)	April
GM 4T65-E: 1811 & 741 codes (Torque Converter Tech Tips)	October
GM 4T65-E: no TCC application (Shift Pointers)	April

GM 6T75: Code P0797 - pressure control solenoid C stuck off (Shift Pointers)	February
GM transfer cases: Electronic diagnosis (Up to Standards)	June
GM trucks with independent front suspension, 1983 up: Revised front drive axles (Up to Standards)	October
Honda: Shifter stuck in park (As Seen in Tech/Talk)	September
Hyundai F4A40/50: shudder or slip in reverse (As Seen in Tech/Talk)	December
Impeller vanes and weld gaps (Torque Converter Tech Tips)	April
Mazda 5NR5: Redesign of transaxle to add fifth gear (Technically Speaking)	June
Mazda R4A-EL: Cross-connection of electrical components (Technically Speaking)	October
Mercedes: diagnosis of electrical problems (Tech-to-Tech)	April
Mitsubishi F4A40/50: shudder or slip in reverse (As Seen in Tech/Talk)	December
More centerline issues (Torque Converter Tech Tips)	December
New Venture 244 Gen II transfer case: design, operation and diagnosis (Up to Standards)	April
Nissan RE4F04A: Abrupt downshift and upshift (Shift Pointers)	September
NVG 245 transfer case: design, operation and diagnosis (Up to Standards)	November
Oldsmobile Bravada, 1994: No upshift; code 24 (Shift Pointers)	March
Rebuilding planetaries: an easier way (TASC Force Tips)	April
Saab 9-3: Service accessibility and issues (Tech-to-Tech)	March
Solving noise problems in manual transmissions (Up to Standards)	August
Stator-cap wear (Torque Converter Tech Tips)	July
TCC frictions bonded off center (Torque Converter Tech Tips)	November
TCC release clearance (Torque Converter Tech Tips)	January
Temperature setting for bonding TCC pistons (Torque Converter Tech Tips)	June
Toyota A140E: Cross-connection of electrical components (Technically Speaking)	October
Toyota A340, 2002 Tundra: No lockup hot, TCC slip, 0770 code (Torque Converter Tech Tips)	September
Toyota Tacoma, 2000: Transmission malfunction caused by defective tow-package wiring (Technically Speaking)	July
Toyota Tacoma: serviceability report (Tech-to-Tech)	December
Toyota U140/240 series: Common wear-out areas in the valve body (Technically Speaking)	September
Toyota U140/240 series: diagnostic information (TASC Force Tips)	December
Toyota U140/240: Operating characteristics (Technically Speaking)	August
Toyota U140E: Use of incorrect manual valve (Technically Speaking)	December
Toyota/Lexus U140/240: Operational characteristics (Technically Speaking)	August
Transmission rebuilding tips to avoid common problems (TASC Force Tips)	March
Tremec 6060: Design and operation (Up to Standards)	February
Volvo 55-50SN: 740 code (Torque Converter Tech Tips)	October
VW 01M, 2001 Jetta: 740 code (Torque Converter Tech Tips)	September
VW 01M, 2002 Jetta: Dragging 3-4 shift (Technically Speaking)	March
VW 09A (JF506E): Code 00349 - electrical fault for solenoid 10 (Shift Pointers)	January
VW 09G/09M: Cross-connection of electrical components (Technically Speaking)	October
ZF 5HP19/24: Noise caused by worn sprag inner race in stator (Torque Converter Tech Tips)	May
ZF 5HP24 in Audi A8 Quattro: TCC cycling bang (TASC Force Tips)	August
ZF 5HP24: Code P0731 or P1722 - gear-ratio error in first (Technically Speaking)	January
ZF 5HP26 in BMW X5: Flow through pump blocked by melted relief valve (Shift Pointers)	August

Seminar Audio Recordings



Transmission Technical

Technical Package of 6 CDs\$99
Technical Seminars Individually\$19

2008



Shop Management

Shop Management Package of 8 CDs.....\$136
Individual CD orders.....\$19 each

08-T01 ZF 6HP Factory Training

Direct from ZF, Tony Price brings diagnostic and operating knowledge on this emerging and popular family of transmissions.

08-T02 Chrysler 62TE

Wayne Colonna from ATSG gives the industry's first comprehensive look at the unique workings and technology of this unit destined to become a regular in your shop bays.

08-T03 Voltage Drop Testing

Jerry "G" Truglia gives plenty of advice and hints on successfully and efficiently locating the electronic gremlins that haunt the modern day transmission retailer.

08-T04 Toyota U Series Transaxles

Nobody can cram more knowledge into a seminar session than ATSG's Pete Luban. Here is the definitive builder's guide to working on these popular units.

08-T05 Scoping Late-model Fords

Bernie Thompson from Automotive Test Solutions discusses how to test and interpret the Ford data stream. This session is valuable to anyone working on these vehicle powertrains.

08-T06 The Builder's Bench 2008

John Parmenter moves through a number of units that have challenged rebuilders this year. John identifies the problems and then serves up solutions to both diagnostic and rebuilding issues.

08-M01 Profit Structuring: Installing Winning Formulas, Part I

In this Automotive Management Institute-accredited seminar, Maylan Newton enables shop operators to understand, install and use a set of formulas in conducting business that helps them achieve financial goals.

08-M02 Profit Structuring: Installing Winning Formulas, Part II

In Part II of this seminar, Maylan Newton continues with formulas to help shops set the correct flat rate, conduct business based on the cost of doing business, work on formulas to measure productivity, work parts-markup formulas and plan growth strategies.

08-M03 Sid's Steps for Success

Motivational speaker Sid Hurlbert teaches you coping mechanisms to leave exhaustion and cynicism behind, particularly when dealing with customers, co-workers and even family members. He teaches you how to take control and make your workday more enjoyable.

08-M04 Performance Parts & the Magnuson-Moss Act

Undercar Digest Management Matters Author Tom Langer, Larry Norris of MagnaFlow and Muffler & Pipe Advice author Ed Hanson discuss the dos and don'ts of aftermarket performance parts and how they affect a vehicle's manufacturer warranty.

08-M05 Dealing with Those Pesky Telephone Price Shoppers

Transmission Digest Business Editor Terry Greenhut shows you the best techniques to handle price shoppers over the phone and persuade them to set up an appointment so a technician can determine what is actually wrong with their vehicle instead of quoting a price for an undiagnosed service.

08-M06 Business Management for Automotive Service Businesses

Undercar Digest Management Matters author Tom Langer sets the framework for shops to help you set up a business plan that really works.

08-M07 Cashing In on Classics

Management Matters author Tom Langer, Muffler & Pipe Advice author Ed Hanson, Huth's Joe Becker, Eaton Leonard Tooling's Paul Howard, Packard Industries' Fred Kanter and vehicle restorer and museum owner Dennis Moran discuss how classics and muscle cars can provide an additional profit center for shops.

08-M08 5 Seconds to Success

Motivational Speaker Sid Hurlbert shares some secrets that very few businesses understand. In less than 5 seconds you can determine how customers, co-workers and even family members are going to view and treat you. Sid combines humor with remedies that can make your business prosper.

HANDOUTS ON CD
PDF Format includes
Management and Transmission
Technical session materials
distributed.
\$50

Visa and MasterCard Accepted

U.S. Orders:
Includes Postage & Handling
Allow 4 to 6 weeks for delivery

International Orders:
Please inquire for shipping charges



Phone: 417-866-3917
800-274-7890
Fax: 417-866-2781
Mail: PO Box 2210
Springfield, MO 65801-2210
E-mail: editor@mdpublications.com

Make Checks payable to: M D Publications, Inc.